



Longborough HLO20, The Monarchs Way, Gloucestershire, Cotswolds.

Before and after photos



Above: The worst section at the top of the path where a year-round puddle had formed obstructing passage by anyone wearing less than wellies has been scraped, regraded and stoned with a fall to the side so any water is shed rather than captured as standing water on the path.

Below: the muddy approach to the gateway has also been scraped and regraded and stoned.





Above. The slope up the hill has been cleared of encroaching to increase the usable path width and prevent concentrated use that was contributing to gullying. It has been regraded down towards the newly dug ditch which will take excess water away from the path to try and prevent it running along the path as it was doing so before.



Above and on the next page: The bottom section of the path has been scraped and built up with stone to provide a higher surface for users to be above any flooded areas yet still allow the water to drain away naturally.

